

मानक भवन,9 बहादुरशाह जफर मार्ग नई, दिल्ली-110002 Manak Bhavan ,9 Bahadur Shah Zafar Marg, New Delhi-110002 Phones: 23230131 / 23233375 / 23239402 Website: www.bis.org.in , www.bis.gov.in

(Ministry of Consumer Affairs, Food & Public Distribution, Govt. of India)

Review Document Basic Details 1. Sectional Committee No. & Title: FAD 11 - Agricultural Machinery and Equipment 2. IS No : IS H9877 : 1981 Code of practice for installation, operation and preventive maintenance of grain 3. Title : combine (HINDI) October, 2016 4. Date of Previous Review:

Review Analysis								
5.1 Status of standard(s), if any from which assistance had been drawn in the formulation of this IS.								
S.No.	Standard (No.)	Standard (Title)	Whether the standard has since been revised Major changes			Action proposed		
No entry made in this table								
5.2 Status of standard referred in the IS.								
S.No.	Referred standards (No.)	Referred standards (Title)	Since revised IS no. of the corresponding IS	Changes in the referred Standards since last review of IS			Action proposed	
No entry made in this table								
5.3 Any other standards available related to the subject & scope of the standard being reviewed (International/regional/other national/association/consortia, etc or of new or revision of existing Indian Standard).								
S.No.	S	andard (No.)	Standard (Title)	Provisions that could be relevant while reviewing the IS		Action proposed		
No entry made in this table								
5.4 Technical comments on the standard received, if any.								
S.No.	S.No. Source (Clause of IS	Comment Action		proposed		
No entry made in this table								

S.No.	Source	Source Development Relevant clause of		lause of the IS under review that is l	the IS under review that is likely to be impacted (Clause & IS No.)				
	No entry made in this table								
5.6 Issues arising out of changes in any related IS or due to formulation of new Indian Standard.									
S.No.	Related IS Related IS wou		Provision in the IS under review would be impacted & the clause addition of new clause/provision		Action proposed				
No entry made in this table									
5.7 Any consequential changes to be considered in other IS.									
5.7 Any	S.No. Related IS to get impacted					Requirements to be impacted			

Other Details						
6.	Any other observation:					
7.	Upload Supporting Document(s)					
7.1	ARP Report	61_21042_230320010811_ARP_Report.pdf				
7.2	2 Draft Document	<u>61_21042_230320010811_Draft_Document.pdf</u>				
 Recommendations - On the basis of the analysis of mentioned above consideration of sectional comm the following aspects of the IS under review: 			IS 9877 : 1981 Code of Practice for Installation, Operation and Preventive Maintenance of Grain Combine was reviewed and reaffirmed in April 2021. As IS H9877: 1981 is hindi version of IS 9877, it is also reaffirmed.			