

मानक भवन, 9 बहादुरशाह जफर मार्ग नई, दिल्ली-110002 Manak Bhavan ,9 Bahadur Shah Zafar Marg, New Delhi-110002 Phones: 23230131 / 23233375 / 23239402 Website: www.bis.org.in , www.bis.gov.in

Revi	iew I	Documen	t						
Basic	Detai	ls							
	Sec	Sectional Committee No. & Title:			TED 11 - Automotive Elec	trical Equipment and	d Instrume	nts	
	IS N	No:			IS 2577 : Part 5 : 2018				
	Title:			Road Vehicles - Fuse Links Part 5 Links with Axial Terminals (Strip Fuse-links) Types SF30 and SF51 and Test Fixtures (Third Revision)					
	Date of Previous Review:			September, 2017					
Revie	w Ana	alysis							
5.1	Statu	s of standard	(s), if any from which	assistance had been drawn in	the formulation of this IS.				
S.N	lo.	Standard (N	(o.) Standard (Title	e) Whether the standard	Whether the standard has since been revised		Major changes Actio		
			·	No entry mac	le in this table				
5.2 Status of standard referred in the IS.									
S.N	lo.	Referred standards (N	Referred standards (Title)	Since revised IS no. of the corresponding IS	Changes in the referred Standards since last review of IS	Changes in the referred stand which are affe standard unde	lard cting the	Action proposed	
No entry made in this table									
5.3 nat	Any o	other standard	ds available related to onsortia, etc or of new	the subject & scope of the star or revision of existing Indian	ndard being reviewed (Interi Standard).	national/regional/o	ther		
S.No.			Standard (No.)	Standard (Title)	Provisions that could be relevant while reviewing the IS		Action	Action proposed	
				No entry mac	le in this table				
5.4	Techi	nical commen	ts on the standard reco	eived, if any.					
S.No. Source		Clause of IS	Clause of IS Comment		Action proposed				
				No entry mad	le in this table	<u> </u>			

5.5 Information available on relevant technical developments					
S.No.	Source	Development	Relevant clause of the IS under review that is likely to be impacted (Clause & IS No.)	Action proposed	
	No entry made in this table				

5.6 Issues arising out of changes in any related IS or due to formulation of new Indian Standard.							
S.No.	Related IS (revised or new)	Related IS Title	Provision in the IS under review that would be impacted & the clause no. or addition of new clause/provision	Changes that may be necessary in the Standards under review	Action proposed		
	No entry made in this table						

5.7 Any consequential changes to be considered in other IS.					
S.No.	Related IS to get impacted	Related IS Title	Requirements to be impacted		
No entry made in this table					

Other Details					
6.	Any other observation:				
7.	7. Upload Supporting Document(s)				
7.1	ARP Report	67_21676_230803041157_ARP_Report.docx			
7.2 Draft Document		No Document Uploaded			
Recommendations - On the basis of the analysis of the in mentioned above consideration of sectional committee is the following aspects of the IS under review:			IS 2577 (Part 5):2018 is identical adoption of ISO 8820-5:2015. It is proposed that IS 2577 (Part 5):2018 may be taken up for revision as and when ISO Standard is taken up for revision.		