

**BUREAU OF INDIAN STANDARDS
CENTRAL LABORATORY
MECHANICAL LAB**

Our Ref: CL/Mech/Facility

Date: 18/09/2023

Subject: Test Facility Out of Order


This is for the information of all concerned that CL, Mechanical Section will not be able to test as per Cl.4.6.3 of IS 15410:2003 (Vibration Leakage) in accordance with the Cl.6.2 of IS 2798:1998 as Vibration Leakage Test Apparatus is under breakdown/ out of order. BOs are requested to take the same into consideration while sending samples.


18/09/23

Vishal Kumar

Scientist-B & OIC(M)

Head (CL)


18/09/23

Copy to ITS (For hosting on intranet)


**भारतीय मानक ब्यूरो
केन्द्रीय प्रयोगशाला
यांत्रिक प्रयोगशाला**

हमारा संदर्भ: सीएल/मेक/सुविधा

दिनांक: 18/09/2023

विषय: परीक्षण सुविधा खराब


यह सभी संबंधितों की जानकारी के लिए है कि सीएल, मैकेनिकल अनुभाग IS 15410:2003 (कंपन रिसाव) के Cl.4.6.3 के अनुसार IS 2798:1998 के Cl.6.2 के अनुसार कंपन रिसाव के रूप में परीक्षण नहीं कर पाएगा। परीक्षण उपकरण खराब/ खराब है। बीओ से अनुरोध है कि वे नमूने भेजते समय इसे ध्यान में रखें।


18/09/23

विशाल कुमार

वैज्ञानिक-बी एवं ओआईसी(एम)

प्रमुख (सीएल)


18/09/23

आईटीएस में कॉपी करें (इंट्रानेट पर होस्टिंग के लिए)