<u>केन्द्रीय मुहर विभाग - III</u>

हमारा संदर्भ- केन्द्रीय मुहर विभाग-III/16: IS 458

15 10 2019

विषय: आईएस 458: 2003 के अनुसार प्रोडक्ट मैन्युअल के कार्यान्वयन के संदर्भ में

सभी शाखा कार्यालय से आग्रह है कि उपरोक्त विषय से संबंधित संलग्न परिपत्र का अवलोकन करें।

(एस डी राणे) वैज्ञानिक 'ई' (सी एम डी-III)

प्रमुख (सी एम डी-III)

सभी क्षेत्रीय/शाखा कार्यालय

आई टी एस विभाग — बीआईएस इंट्रानेट पर अपलोड करने हेतू

CENTRAL MARKS DEPARTMENT-III

Our Ref: CMD-III/16: IS 458 15 10 2019

Subject: Implementation of Product Manual as per IS 458: 2003

BOs may kindly see the attached circular on the subject mentioned above.

(S D Rane) Sc-E (CMD III)

Head (CMD - III)

Circulated to: All ROs/BOs

Copy to: ITSD – For hosting on Intranet

CENTRAL MARKS DEPARTMENT -III

Ref: CMD-III/ 16: 458 15 October 2019

Subject: Implementation of Product Manual Doc: PM/IS 458/1/December 2018 for certification of IS 458: 2003.

This has reference to the above subject. Product manual doc: PM/IS 458/1/December 2018 was circulated by CMD-III on 12/12/2018 for implementation. As per IS 458: 2003, conformity of reinforcement is required to be ensured as per relevent Indian Standard. HD wire as per IS 432 (Part 2): 1982 is also used as reinforcement in manufacturing of precast concrete pipes, which is under mandatory certification of BIS as per Steel and Steel Products (Quality Control) Orders, 2019.

CMD-III received a representation from M/s Spun Pipes Manufacturing Association of Maharashtra with request for keeping implementation of product manual with SIT in abeyance citing non availability of ISI marked HD wire as per IS 432 (Part 2). They also informed that manufacturers of HD wire are not taking BIS licence for their product and hence supply position of 11 licensees as per IS 432 (Part 2) does not cater to the demand from more than 600 manufacturers of precast concrete pipes. However, as the HD wire as per IS 432 (Part 2): 1982 is under mandatory certification, BIS cannot relax any provisions of the QCO and cannot grant permission to use non-ISI raw material.

In view of the above, BOs are requested to follow up with manufactures of HD wire located under their jurisdiction for making them aware about obtaining BIS licence. BOs are also requested to take appropriate action against manufacturers of HD wire who have not implemented the provisions of Steel and Steel Products (Quality Control) Orders, 2019.

This issues with approval of DDG (Certification).

(S D Rane) Sc-E (CMD-III)

Head (CMD-III)

DDG (Certification)

Circulated to: All BOs