BUREAU OF INDIAN STANDARDS

(Southern Regional Office Laboratory)

Our Ref:SROL/Electrical13/06/2018

Subject: Acute shortage of samples at SROL (Electrical Section)

The following samples may be rushed to SROL as the testing facility remains under-utilized due to shortage of samples:

S No	IS No	S No	IS No
1	IS 694	6	IS 398(Part 2)
2	IS 14255	7	IS 398(Part 4)
3	IS 1554(Part 1)	8	IS 398(Part 5)
4	IS 7098 (part 1)	9	IS 9537(Part 3)
5	IS 398(Part 1)	10	IS 4250

For partial/complete test facility status please refer BIS website.

(TrinadhKothapalli)
OIC(Electrical)

H(SROL)

Copy to: LPPD

All BOs, All Labs

ITSD- With a request to host on BIS intranet

अतिआवश्यक

भारतीयमानकब्यूरो (दक्षिणी क्षेत्रीय कार्यालय प्रयोगशाला)

हमारासंदभा: SROL/Electrical 13 June 2018

बिषय: SROL(विद्युत परीक्षणअनुभाग)परनमूनेकीभारीकमी

दक्षिणी क्षेत्रीय कार्यालय प्रयोगशालाकेविद्युत परीक्षण अनुभागमेनमन्ेकीभारीकमीहोगईहैअतःआपसेअन्रोधहैकीनिम्नलिखितआईएसएसकेनमन्रेअधिकसेअ धिकमात्रामेंहमेंभेजनेकाकष्टकरें।

S No	IS No	S No	IS No
1	IS 694	6	IS 398(Part 2)
2	IS 14255	7	IS 398(Part 4)
3	IS 1554(Part 1)	8	IS 398(Part 5)
4	IS 7098 (part 1)	9	IS 9537(Part 3)
5	IS 398(Part 1)	10	IS 4250

पूर्ण/आंशिकपरिक्षणसुविधाकेलिएभारतीयमानकब्यूरोकीवेबसाइटदेखनेकीकृपाकरे

(त्रिनाधकोतपल्ली)

प्रभागिअधिकारी(विद्युत परीक्षण अनुभाग)

वै. ई. एवंप्रमुख, यसरवोल

प्रतिलिपि: एलपीपीडी

सभीसखाकार्यालय/सभीप्रयोगशाला

आईटीएस :कृपयाइसपरिपत्रकोभारतीयमानकब्यूरोकेइंट्रानेटपैरअपलोडकरे।