### **BUREAU OF INDIAN STANDARDS**

### **Program of Work**

#### **CED 13: Building Construction Practices**

Scope: DRAWING UP OF CODES OF PRACTICE FOR BUILDING CONSTRUCTION AND

MAINTENANCE.

Liaison: ISO TC-165 (P): Timber structures ISO TC-59 (O): Buildings and civil engineering works ISO

TC-59 SC-13 (O): Organization and digitization of information about buildings and civil

engineering works, including building information modelling (BIM) ISO TC-59

SC-2 (O): Terminology and harmonization of languages ISO TC-59 SC-8 (O): Sealants

### **Published Standards**

S.No	IS No.	TITLE	Reaffirm M-Y	No. of Amds	Eqv.
1	IS 10388 : 1982	Corrugated coir wood wool cement	September, 2020	-	Indigenous
	Reviewed In: 2020	roofing sheets-Specification			
	Reaffirmed but not				
	taken up for revision				
2	IS 10439 : 1983	Code of practice for patent glazing	September, 2020	-	
	Reviewed In: 2020				
3	IS 10440 : 1983	Code of practice for construction	September, 2020	-	Indigenous
	Reviewed In: 2020	of RB and RBC floors and roofs			
4	IS 10566 : 1983	Methods of tests for preformed	September, 2020	-	Indigenous
	Reviewed In: 2020	fillers for expansion joints in			
		concrete paving and structural			
	IC 10057 1000	construction	G . 1 2024		T1 2 1 1 1 1
5	IS 10957 : 1999	Joints in buildings - Vocabulary,	September, 2024	-	Identical under dual
	ISO 2444 Reviewed In: 2024	(First Revision)			numbering
	ISO 2848:1984				
6	IS 10958 : 1984	General check list of functions of	March, 2023		Identical under dual
6	ISO 3447	joints in building (ISO Title : Joints	March, 2023	-	numbering
	Reviewed In: 2023	In Building - General Check - List			numbering
	ISO 4447:1975	Of Joint Functions)			
7		Sealants for Building Purposes â€"		_	Identical under dual
'	ISO 6927 : 2021	Glossary of Terms (Second			numbering
	ISO 6927 : 2021	Revision)			numbering
8	IS 11096 : 1984	Code of practice for design and	September, 2020	_	Indigenous
	Reviewed In: 2020	construction of bolt jointed timber			
		construction			
9	IS 11134 : 1984	Code of practice for setting out of	September, 2020	-	Modified/Technically
	Reviewed In: 2020	buildings	•		Equivalent
	ISO 4463				
10	IS 11433 (Part 1):	Specification for one part gun-	September, 2020	-	Indigenous
	1985	grade polysulphide- based joints			
	Reviewed In: 2020	sealants Part 1 General			
		requirements			
				1	

11	IS 11433 (Part 2):	Specification for one part gun-	September, 2020	1 -	Indigenous
''	1986	grade polysulphide- based joint	September, 2020	_	margenous
	Reviewed In: 2020	sealants:Part 2 Methods of test			
12	IS 11817 : 1986	Classification of joints in buildings	March, 2023	-	Identical under dual
		for accommodation of dimensional			numbering
	Reviewed In: 2023	- Deviations during construction			
	ISO 7727:1984	(ISO Title : Joints In Building -			
		Principles For Jointing of Building			
		Components - Accommodation Of			
		Dimensional Deviations During			
12	10 11010 1006	Construction)	1 2022		X1 2 1 1 1 1
13	IS 11818 : 1986	Method of test for laboratory	March, 2023	-	Identical under dual
	ISO 6589 Reviewed In: 2023	determination of air permeability of joints in building (ISO Title :			numbering
	ISO 6589:1984	Joints In Building - Laboratory			
	130 0389.1984	method of test for air permeability			
		of joints)			
14	IS 12093 : 1987	Code of Practice for Laying and	March, 2023	-	
	Reviewed In: 2023	Fixing of Sloped Roof Coverings	,		
	Reaffirmed but not	Using Plain and Corrugated			
	taken up for revision	Galvanized Steel Sheets			
15	IS 12118 (Part 1):	Specification for two - Part	March, 2023	-	Indigenous
	1987	polysulphide - Based sealants: Part			
16	Reviewed In : 2023	1 general requirements	N. 1. 2022		Υ 1'
16	IS 12118 (Part 2):	Specification for two - Part	March, 2023	-	Indigenous
	1987 Reviewed In : 2023	polysulphide - Based sealants: Part 2 methods of tests			
17	IS 12506 : 1988	Code of practice for improved that	September, 2019		Indigenous
''	Reviewed In: 2019	ching of roof with rotand fire	September, 2017		margenous
	Reaffirmed but not	retardant - Treatment			
	taken up for revision				
18	IS 12727 : 1989	No - Fines cast in situ cement	September, 2020	-	Indigenous
10	Reviewed In: 2020	concrete - Code of practice			
19	IS 13077 : 1991	Guide for preparation and use of	August, 2021	-	
	Reviewed In: 2021 Reaffirmed but not	mud mortar in masonary			
	taken up for revision				
	taken up for fevision				
20	IS 1414 : 1989	Fixing of wall coverings - Code of	September, 2024	-	Indigenous
	Reviewed In: 2024	practice (First Revision)			
21	IS 14428 : 1997	Painting of structures in aggressive	May, 2023	-	Indigenous
		chemical environment - Guidelines			
22	IS 1477 (Part 1):	Code of practice for painting of	September, 2020	-	Indigenous
	1971	ferrous metals in buildings: Part 1			
	Reviewed In: 2020	pretreatment (First Revision)	Cambo 1 2000		Tar Attacher
23	IS 1477 (Part 2): 1971	Code of practice for painting of	September, 2020	-	Indigenous
	Reviewed In: 2020	ferrous metals in buildings: Part 2 painting (First Revision)			
24	IS 15183 (Part 1):	Maintenance Management of	September, 2022	_	Indigenous
-	2018	Buildings — Guidelines Part 1	50ptomoor, 2022		margonous
		General (First Revision			
L	Reviewed In: 2022	,			
25	IS 15183 (Part 2):	Maintenance Management of	September, 2022	-	Indigenous
	2018	Buildings — Guidelines Part 2			
		Finance (First Revision)			
	Reviewed In : 2022		0 1 2022		Y 1'
26	IS 15183 (Part 3):	Maintenance Management of	September, 2022	-	Indigenous

1	2018	Buildings — Guidelines Part 3		1 1	
		Labour ( First Revision )			
	Reviewed In: 2022				
27	IS 15345 : 2003	Installation of Frameless Door and	May, 2023	-	
	Reviewed In: 2023	Window Shutters - Code of			
20	IC 15012 2010	Practice	L-1 2022		T., 12
28	IS 15912 : 2018	Structural design using bamboo - Code of practice (First Revision)	July, 2022	-	Indigenous
	Reviewed In: 2022	Code of practice (Prist Revision)			
29	IS 1597 (Part 1):	Construction of stone masonry -	December, 2021	-	Indigenous
	1992	Code of practice: Part 1 rubble	2000111, 2021		1114150110410
	Reviewed In: 2021	stone masonry (First Revision)			
30	IS 1597 (Part 2):	Construction of stone masonry -	December, 2021	-	Indigenous
	1992	Code of practice: Part 2 ashlar			
	Reviewed In: 2021	masonry (First Revision)			
31	IS 16231 (Part 1):	Use of Glass in Buildings — Code	January, 2024	-	Indigenous
	2019	of Practice Part 1 General			
	Reviewed In: 2024	Methodology for Selection ( First Revision )			
32	IS 16231 (Part 2):	Use of Glass in Buildings — Code	January, 2024	_	Indigenous
	` '	of Practice Part 2 Energy and Light	Junuary, 2027		margonous
		( First Revision )			
	Reviewed In: 2024	, , ,			
33	IS 16231 (Part 3):	Use of Glass in Buildings — Code	January, 2024	-	Indigenous
	2019	of Practice Part 3 Fire and Loading			
		( First Revision )			
	Reviewed In: 2024				
34	IS 16231 (Part 4):	Use of Glass in Buildings — Code	January, 2024	-	Not Equivalent
	2019	of Practice Part 4 Safety Related to			
	Reviewed In: 2024	Human Impact ( First Revision )			
	nil				
35	IS 1634 : 1992	Code of practice for design and	December, 2021	-	
	Reviewed In: 2021	construction of wood stairs for			
	Reaffirmed but not	houses (Second Revision)			
	taken up for revision				
2.6	X0 1 6 10 10 60				* "
36	IS 1649 : 1962	Code of practice for design and	March, 2023	-	Indigenous
	Reviewed In: 2023	construction of flues and chimneys for domestic heating appliances			
37	SP 1650 : 1973	Standard colours for building and		_	Indigenous
	Reviewed In : 2005	decorative finishes			margonous
38	SP 1650 : 1973	Standard colours for building and		-	Indigenous
	Reviewed In: 2000	decorative finishes			
39	IS 1834 : 1984	Hot Applied Sealing Compounds	September, 2020	-	Indigenous
	Reviewed In: 2020	for Joints in Concrete-			
40	IG 1000 (B. 14)	Specification (First Revision)	0 . 1 2020	1	Τ 1'
40	IS 1838 (Part 1):	preformed fillers for expansion	September, 2020	1	Indigenous
	1983 Reviewed In : 2020	joint in concrete pavement and			
	Kevieweu III : 2020	structures (non extruding and resilient type): Part 1 Bitumen			
		impregnated fibre - Specification			
41	IS 1838 (Part 2):	preformed fillers for expansion	September, 2020	-	Not Equivalent
	1984	joint in concrete pavement and	1 /		1
	Reviewed In: 2020	structure (non extruding and			
		resilient type) Part 2 CNSL			
		Aldehyde resin and coconut pith -			
42	IC 1020 (D + 2)	Specification	D 1 2021	1	T., 11
42	IS 1838 (Part 3):	Preformed Fillers for Expansion	December, 2021	1	Indigenous

	2011	Joints in Concrete Pavements and				
	Reviewed In: 2021	Structures(non-extruding and				
		resilient type) Part 3 Polymer Based				
43	IS 1905 : 1987	Code of practice for structural use	January, 2023	1	Indigenous	
15	Reviewed In: 2023	of unreinforced masonry (Third	Junuary, 2023	1	margenous	
		Revision)				
44	IS 1946 : 1961	Code of practice for use of fixtng	January, 2023	-	Indigenous	
	Reviewed In: 2023	devices in walls, ceilings and floors			inaigenous	
		of solid construction				
45	SP 20 : 1991	Handbook on masonry design and		-	Indigenous	
		construction (First Revision)				
46	SP 21 : 2005	Summaries of indian standards for		-	Indigenous	
47	IC 0110 1000	building materials (First Revision)	1 2022		T 1'	
47	IS 2110 : 1980	Code of practice for in situ	January, 2023	-	Indigenous	
	Reviewed In: 2023	construction of walls in buildings with soil - Cement (First Revision)				
48	IS 2115 : 1980	Code of practice for flat roof	January, 2023		Indigenous	
+0	Reviewed In : 2023	finish: mud phuska	January, 2023	<u> </u>	murgenous	
49	IS 2118 : 1980	Code of practice for construction	January, 2023	_	Indigenous	
	Reviewed In: 2023	of jack - Arch type of built - Up	· · · · · · · · · · · · · · · · · · ·		margenous	
		floor or roof (First Revision)				
50	IS 2119 : 1980	Code of practice for construction	January, 2023	-	Indigenous	
	Reviewed In: 2023	of brick - Cum - Concrete				
		composite (Madras Terrace) floor				
		and roof				
51	IS 2204 : 1962	Wooden cross arms - Specification	September, 2020	-	Indigenous	
	Reviewed In: 2020	(Second Revision)				
52	IS 2212 : 1991	Brick works - Code of practice	September, 2024	-	Indigenous	
52	Reviewed In: 2024 IS 2250: 1981	(First Revision)	Camtaurhan 2020		To di como co	
53	Reviewed In : 2020	Code of practice for preparation and use of masonry mortars (First	September, 2020	-	Indigenous	
	Reviewed III . 2020	Revision)				
54	IS 2338 (Part 1):	Code of practice for finishing of	September, 2020	_		
J.	1967	wood and wood based materials:	September, 2020	-		
	Reviewed In: 2020	Part 1 Operations and				
		workmanship				
55	IS 2338 (Part 2):	Code of practice for finishing of	September, 2020	-		
	1967	wood and wood based materials:				
	Reviewed In: 2020	Part 2 Schedules				
56	IS 2366 : 1983	Code of practice for nail-jointed	September, 2020	-		
	Reviewed In: 2020	timber construction	0.004			
57		Painting of Concrete, Masonry and	September, 2024	-		
	1994 Reviewed In : 2024	Plaster Surfaces - Code of Practice				
	Reviewed III: 2024	- Part 1 : Operations and Workmanship				
58	IS 2395 (Part 2):	Code of practice for painting	September, 2024	<u> </u>		
20	1994	concrete, masonry and plaster	56ptc1110c1, 2024			
	Reviewed In: 2024	surfaces: Part 2 Schedules (First				
		Revision)				
59	IS 2441 : 1984	Code of practice for fixing ceiling	September, 2020	-	Indigenous	
	Reviewed In: 2020	coverings (First Revision)	<del>-</del> 			
60	SP 25(S&T): 1984	Handbook on causes and		-	Indigenous	
		prevention of cracks in building				
61	IS 2524 (Part 1):	Code of practice for painting of	September, 2020	-	Indigenous	
	1968	non - Ferrous metals in buildings:				
60	Reviewed In: 2020	Part 1 pretreatment	Contambo 2020	1	Te diamen-	
62	IS 2524 (Part 2): 1968	Code of practice for painting of non - Ferrous in buildings: Part 2	September, 2020	- I	Indigenous	
	1900	non - retrous in buildings. Fait 2				
		•				

	Reviewed In: 2020				
63	IS 2527 : 1984	Code of practice for fixing	September, 2020	-	Indigenous
	Reviewed In: 2020	rainwater gutters and downpipes			
64	IS 2700 : 1987	for roof drainage (First Revision)	Santambar 2020		Indiannous
34	Reviewed In : 2020	Code of practice for roofing with wooden shingles (First Revision)	September, 2020	-	Indigenous
65	IS 2792 : 1964	Code of practice for design and	September, 2020	_	Indigenous
,,		construction of stone slab over joist	September, 2020		margenous
	Reaffirmed but not	floor			
	taken up for revision				
	-				
66	IS 2858 : 1984	984 Code of practice for roofing with September, 2020 -		-	Indigenous
	Reviewed In: 2020	mangalore tiles (First Revision)			
67	IS 3140 : 1965	Code of practice for painting	September, 2020	-	
	Reviewed In: 2020	asbestos cement building products			
	Reaffirmed but not				
	taken up for revision				
58	SP 33 : 1986	Handbook on Timber Engineering			
,,	31 33 . 1980	Trandook on Timber Engineering		_	
59	IS 3414 : 1968	Code of Practice for Design and	September, 2020	_	
	Reviewed In: 2020	Installation of Joints in Buildings	50p.00m.001, 2020		
70	IS 3548 : 1988	Code of Practice for Glazing in	September, 2024	-	
	Reviewed In: 2024	Buildings (First Revision)	•		
71	IS 3629 : 1986	Structural Timber In Building -	September, 2020	-	Indigenous
	Reviewed In: 2020	Specification			
72	IS 3630 : 1992	Construction Of Non-load Bearing	December, 2021	-	
	Reviewed In: 2021	Gypsum Block Partitions - Code			
	XG 2 (#2) 4000	Of Practice	2020		
73	IS 3670 : 1989	Code of practice for construction	September, 2020	-	
7.4	Reviewed In : 2020	of timber floors	C11 2020		T., 4
74	IS 4101 (Part 1): 1967	Code of practice for external facings and veneers: Part 1 stone	September, 2020	-	Indigenous
	Reviewed In: 2020	facing			
75	IS 4101 (Part 2):	Code of practice for external	September, 2020	_	Indigenous
, 5		facings and veneers: Part 2 cement	September, 2020		margenous
	Reviewed In: 2020	concrete facing			
76	IS 4101 (Part 3):	Code of Practice for External	September, 2020	-	
	1985	Cladding - Part 3: Wall Tiling and	•		
	Reviewed In: 2020	Mosaics			
77	IS 4407 : 1967	Code of practice for reed walling	January, 2023	-	Indigenous
	Reviewed In: 2023				
78	IS 4597 : 1968	Code of Practice for Finishing of	September, 2020	-	Indigenous
	Reviewed In: 2020	Wood And Wood Based Products			
		with Nitrocellulose and Cold			
70	IC 4001 - 1000	Catalysed Materials	Contornal and 2024	<del>                                     </del>	Ta di
79	IS 4891 : 1988 Reviewed In : 2024	Specification for preferred cut sizes of structural timber (First	September, 2024	-	Indigenous
	Kevieweu III : 2024	Revision)			
80	IS 4920 : 1968	Glossary of terms applicable to	September, 2020	_	Indigenous
, 0	Reviewed In : 2020	roof coverings	50ptember, 2020		maigenous
31	IS 4924 (Part 1):	Method of test for nail - Jointed	September, 2020	-	Indigenous
	1968	timber trusses: Part 1 destructive	• '		S
	Reviewed In: 2020	test			
32	IS 4924 (Part 2):	Method of test for nail - Jointed	September, 2020	-	Indigenous
	1968	timber trusses: Part 2 proof test			
	Reviewed In: 2020				
33	IS 4983 : 1968	Code of Practice for Design and	September, 2020	1	
	Reviewed In: 2020	Construction of Nailed Laminated			

0.4	IC 5110 (D + 1)	Timber Beams	9 1 2020		T 1	
84	IS 5119 (Part 1):	Code of practice for laying and	September, 2020	-	Indigenous	
		fixing of sloped roof covering: Part				
	Reviewed In: 2020 IS 5389: 1969	1 slating	I 2022			
35		Code of practice for laying of	January, 2023	-		
	Reviewed in: 2023	hardwood parquet and wood block				
26	IC 5200 1004	floors	C11 2020			
36	IS 5390 : 1984	Code of practice for construction	September, 2020	-		
7.7	Reviewed In: 2020	of timber ceilings	Y 2022		T 1'	
37	IS 6061 (Part 1):	Code of practice for construction	January, 2023	-	Indigenous	
	1971	of floor and roof with joists and				
	Reviewed In: 2023	filler blocks: Part 1 with hollow				
20	concrete filler blocks		<b>.</b>			
88	IS 6061 (Part 2):	Code of practice for construction	September, 2020	-	Indigenous	
of floor and roof with joist and						
	Reviewed In: 2020	filler blocks: Part 2 with hollow				
		clay filler blocks (First Revision)				
39	` ′	Construction of floor and roof with	January, 2023	-	Indigenous	
	1981	joists and filler blocks: Part 3 with		1		
	Reviewed In: 2023	precast hollow clay block joists and		1		
		hollow clay filler blocks				
90	IS 6061 (Part 4):	Code of practice for construction	January, 2023	-	Indigenous	
	1981	of floor and roof with joists and				
	Reviewed In: 2023	filler blocks: Part 4 with precast				
		hollow clay block slab panels				
91	SP 62:1997	Handbook on causes and		-	Indigenous	
		prevention of cracks in buildings				
92	IS 6313 (Part 1):	Code of practice for anti-termite	September, 2020	-		
	1981	measures in buildings: Part 1				
	Reviewed In: 2020	Constructional measures				
93	IS 6313 (Part 2):	Code of Practice for Anti-Termite		-	Indigenous	
	2022	Measures in Buildings - Part 2 : Pre-				
		Constructional Chemical				
		Treatment Measures fourth				
		revision				
94	IS 6313 (Part 3):	Code of Practice for Anti-Termite		-	Indigenous	
	13 0313 (Fait 3).				1110150110010	
	2022	Measures in Buildings Part 3:			margeness	
	, ,				marganous	
	, ,	Measures in Buildings Part 3 : Treatment for Existing Buildings			margeness	
95	, ,	Measures in Buildings Part 3: Treatment for Existing Buildings IS 6313 part 3(Fourth Revision)	September, 2020	-	inaigeness	
	2022	Measures in Buildings Part 3: Treatment for Existing Buildings IS 6313 part 3(Fourth Revision) Code of practice for construction	September, 2020	-	magenous	
	2022 IS 6332 : 1984	Measures in Buildings Part 3: Treatment for Existing Buildings IS 6313 part 3(Fourth Revision) Code of practice for construction of floor and roofs using precast	September, 2020	-	margeness	
	2022 IS 6332 : 1984 Reviewed In : 2020	Measures in Buildings Part 3: Treatment for Existing Buildings IS 6313 part 3(Fourth Revision) Code of practice for construction of floor and roofs using precast doubly-curved shell units	-	-		
95	2022 IS 6332 : 1984 Reviewed In : 2020	Measures in Buildings Part 3: Treatment for Existing Buildings IS 6313 part 3(Fourth Revision) Code of practice for construction of floor and roofs using precast doubly-curved shell units Code of practice for Installation of	September, 2020 September, 2020	-	Indigenous	
95	2022  IS 6332: 1984 Reviewed In: 2020  IS 6509: 1985	Measures in Buildings Part 3: Treatment for Existing Buildings IS 6313 part 3(Fourth Revision) Code of practice for construction of floor and roofs using precast doubly-curved shell units	-	-		
95 96	2022  IS 6332: 1984 Reviewed In: 2020  IS 6509: 1985	Measures in Buildings Part 3: Treatment for Existing Buildings IS 6313 part 3(Fourth Revision) Code of practice for construction of floor and roofs using precast doubly-curved shell units Code of practice for 1nstallation of joints in concrete pavements (First Revision)	September, 2020	-		
95 96	2022  IS 6332: 1984 Reviewed In: 2020  IS 6509: 1985 Reviewed In: 2020  IS 7683: 1975	Measures in Buildings Part 3: Treatment for Existing Buildings IS 6313 part 3(Fourth Revision) Code of practice for construction of floor and roofs using precast doubly-curved shell units Code of practice for 1nstallation of joints in concrete pavements (First Revision) Code of practice for design,	-	- -		
95 96	2022  IS 6332: 1984 Reviewed In: 2020  IS 6509: 1985 Reviewed In: 2020  IS 7683: 1975	Measures in Buildings Part 3: Treatment for Existing Buildings IS 6313 part 3(Fourth Revision) Code of practice for construction of floor and roofs using precast doubly-curved shell units Code of practice for 1nstallation of joints in concrete pavements (First Revision) Code of practice for design, fabrication and maintenance of nail-	September, 2020	-		
95 96	IS 6332: 1984 Reviewed In: 2020 IS 6509: 1985 Reviewed In: 2020 IS 7683: 1975 Reviewed In: 2023 Reaffirmed but not	Measures in Buildings Part 3: Treatment for Existing Buildings IS 6313 part 3(Fourth Revision) Code of practice for construction of floor and roofs using precast doubly-curved shell units Code of practice for Installation of joints in concrete pavements (First Revision) Code of practice for design, fabrication and maintenance of nail- jointed timber posts from small	September, 2020	-		
95 96	IS 6332: 1984 Reviewed In: 2020 IS 6509: 1985 Reviewed In: 2020 IS 7683: 1975 Reviewed In: 2023:	Measures in Buildings Part 3: Treatment for Existing Buildings IS 6313 part 3(Fourth Revision) Code of practice for construction of floor and roofs using precast doubly-curved shell units Code of practice for 1nstallation of joints in concrete pavements (First Revision) Code of practice for design, fabrication and maintenance of nail- jointed timber posts from small dimensional timber for overhead	September, 2020	-		
95 96	IS 6332: 1984 Reviewed In: 2020 IS 6509: 1985 Reviewed In: 2020 IS 7683: 1975 Reviewed In: 2023 Reaffirmed but not	Measures in Buildings Part 3: Treatment for Existing Buildings IS 6313 part 3(Fourth Revision) Code of practice for construction of floor and roofs using precast doubly-curved shell units Code of practice for 1nstallation of joints in concrete pavements (First Revision) Code of practice for design, fabrication and maintenance of nail- jointed timber posts from small dimensional timber for overhead electric distribution lines for low	September, 2020	- -		
995 996	IS 6332: 1984 Reviewed In: 2020 IS 6509: 1985 Reviewed In: 2020 IS 7683: 1975 Reviewed In: 2023: Reaffirmed but not taken up for revision	Measures in Buildings Part 3: Treatment for Existing Buildings IS 6313 part 3(Fourth Revision) Code of practice for construction of floor and roofs using precast doubly-curved shell units Code of practice for 1nstallation of joints in concrete pavements (First Revision) Code of practice for design, fabrication and maintenance of nail- jointed timber posts from small dimensional timber for overhead electric distribution lines for low voltage	September, 2020  January, 2023	-	Indigenous	
95	IS 6332: 1984 Reviewed In: 2020 IS 6509: 1985 Reviewed In: 2020 IS 7683: 1975 Reviewed In: 2023: Reaffirmed but not taken up for revision IS 883: 2016	Measures in Buildings Part 3: Treatment for Existing Buildings IS 6313 part 3(Fourth Revision) Code of practice for construction of floor and roofs using precast doubly-curved shell units Code of practice for Installation of joints in concrete pavements (First Revision) Code of practice for design, Fabrication and maintenance of nail- jointed timber posts from small dimensional timber for overhead electric distribution lines for low voltage Design of Structural Timber in	September, 2020	-		
995	IS 6332: 1984 Reviewed In: 2020 IS 6509: 1985 Reviewed In: 2020 IS 7683: 1975 Reviewed In: 2023: Reaffirmed but not taken up for revision IS 883: 2016	Measures in Buildings Part 3: Treatment for Existing Buildings IS 6313 part 3(Fourth Revision) Code of practice for construction of floor and roofs using precast doubly-curved shell units Code of practice for 1nstallation of joints in concrete pavements (First Revision) Code of practice for design, fabrication and maintenance of nail- jointed timber posts from small dimensional timber for overhead electric distribution lines for low voltage Design of Structural Timber in Buildings - Code of Practice (Fifth	September, 2020  January, 2023	-	Indigenous	
995 996 997	IS 6332: 1984 Reviewed In: 2020 IS 6509: 1985 Reviewed In: 2020 IS 7683: 1975 Reviewed In: 2023: Reaffirmed but not taken up for revision IS 883: 2016 Reviewed In: 2021	Measures in Buildings Part 3: Treatment for Existing Buildings IS 6313 part 3(Fourth Revision) Code of practice for construction of floor and roofs using precast doubly-curved shell units Code of practice for 1nstallation of joints in concrete pavements (First Revision) Code of practice for design, fabrication and maintenance of nail- jointed timber posts from small dimensional timber for overhead electric distribution lines for low voltage Design of Structural Timber in Buildings - Code of Practice (Fifth Revision)	September, 2020  January, 2023  December, 2021	- - -	Indigenous	
995 996	IS 6332: 1984 Reviewed In: 2020 IS 6509: 1985 Reviewed In: 2020 IS 7683: 1975 Reviewed In: 2023: Reaffirmed but not taken up for revision IS 883: 2016 Reviewed In: 2021 IS 9472: 1980	Measures in Buildings Part 3: Treatment for Existing Buildings IS 6313 part 3(Fourth Revision) Code of practice for construction of floor and roofs using precast doubly-curved shell units Code of practice for 1nstallation of joints in concrete pavements (First Revision) Code of practice for design, fabrication and maintenance of nail- jointed timber posts from small dimensional timber for overhead electric distribution lines for low voltage Design of Structural Timber in Buildings - Code of Practice (Fifth Revision) Code of practice for laying of	September, 2020  January, 2023	-	Indigenous	
995 996 997 998	IS 6332: 1984 Reviewed In: 2020 IS 6509: 1985 Reviewed In: 2020 IS 7683: 1975 Reviewed In: 2023: Reaffirmed but not taken up for revision IS 883: 2016 Reviewed In: 2021 IS 9472: 1980 Reviewed In: 2023	Measures in Buildings Part 3: Treatment for Existing Buildings IS 6313 part 3(Fourth Revision) Code of practice for construction of floor and roofs using precast doubly-curved shell units Code of practice for Installation of joints in concrete pavements (First Revision) Code of practice for design, Fabrication and maintenance of nail- jointed timber posts from small dimensional timber for overhead electric distribution lines for low voltage Design of Structural Timber in Buildings - Code of Practice (Fifth Revision) Code of practice for laying of mosaic parquet flooring	January, 2023  December, 2021  January, 2023	- - - -	Indigenous  Indigenous  Indigenous	
995 996 997	IS 6332: 1984 Reviewed In: 2020 IS 6509: 1985 Reviewed In: 2020 IS 7683: 1975 Reviewed In: 2023: Reaffirmed but not taken up for revision IS 883: 2016 Reviewed In: 2021 IS 9472: 1980	Measures in Buildings Part 3: Treatment for Existing Buildings IS 6313 part 3(Fourth Revision) Code of practice for construction of floor and roofs using precast doubly-curved shell units Code of practice for 1nstallation of joints in concrete pavements (First Revision) Code of practice for design, fabrication and maintenance of nail- jointed timber posts from small dimensional timber for overhead electric distribution lines for low voltage Design of Structural Timber in Buildings - Code of Practice (Fifth Revision) Code of practice for laying of	September, 2020  January, 2023  December, 2021	- - 2	Indigenous	

		(Revised)			
101	IS 9954 : 1981	Pictorial surface preparation	September, 2020	1	Indigenous
	Reviewed In: 2020	standards for painting of steel			
		surfaces			

# **Standards under Development**

	Projects Approved			
SI. No.	Doc No.	Title		
	No Records Found			

	Preliminary Draft Standards			
SI. No.	Doc No.	Title		
1	CED 13 (26747) Revision	Fixing of wall coverings - Code of practice second revision		
	of: IS 1414:1989			
2	CED 13 (26748) Revision	Painting of ferrous metals in building - Code of practice Part I Pretreatment first revision		
	of: IS 1477:1971			
3	CED 13 (26749) Revision	Painting of ferrous metals in buildings - Code of practice Part 2 painting Second Revision		
	of: IS 1477:1971			
4	CED 13 (26750) Revision	Flat roof finish - Mud Phuska - Code of practice Third Revision		
	of: IS 2115:1980			
5	CED 13 (26751) Revision	Construction of Jack-Arch type built up floor or roof - Code of practice Second Revision		
	of: IS 2118:1980			
6	CED 13 (26752) Revision	Preparation and use of Masonry Mortars - Code of practice Second Revision		
	of: IS 2250:1981			
7	CED 13 (26753) Revision	Finishing of Wood and Wood based materials - Code of practice Part 1 Operations and		
	of: IS 2338:1967	workmanship First Revision		
8	CED 13 (26754) Revision	Painting of Concrete Masonry and Plaster Surfaces - Code of Practice - Part 1 Operations and		
	of: IS 2395:1994	Workmanship First Revision		
9	CED 13 (26755) Revision	Painting of Non - Ferrous metals in buildings - Code of practice Part 1 Pretreatment First		
	of: IS 2524:1968	Revision		
10	CED 13 (26756) Revision	Painting of non - Ferrous in buildings - Code of practice Part 2 painting First Revision		
	of: IS 2524:1968			
11	CED 13 (26757) Revision	Fixing Rainwater Gutters and Downpipes for Roof drainage - Code of practice Second Revision		
	of: IS 2527:1984			
12	CED 13 (26758) Revision	Painting asbestos cement building products - Code of practice First Revision		
	of: IS 3140:1965			
13	CED 13 (26759) Revision	External facings and Veneers - Code of practice Part 1 stone facing First Revision		
	of: IS 4101:1967			
14	CED 13 (26760) Revision	External facings and Veneers - Code of practice Part 2 Cement Concrete Facing First Revision		
	of: IS 4101:1967			
15	CED 13 (26761) Revision	External Cladding - Code of Practice Part 3 Wall Tiling and Mosaics Second Revision		
	of: IS 4101:1985			
16	CED 13 (26762) Revision	Finishing of Wood And Wood Based Products with Nitrocellulose and Cold Catalysed Materials -		
	of: IS 4597:1968	Code of Practice First Revision		
17	CED 13 (26764) Revision	Laying of hardwood parquet and wood block floors - Code of practice First Revision		
	of: IS 5389:1969			
18	CED 13 (26765) Revision	Anti-termite measures in buildings - Code of practice Part 1 Constructional measures Second		
	of: IS 6313:1981	Revision		
19	CED 13 (26766) Revision	Construction of RB and RBC floors and roofs - Code of practice First Revision		
	of: IS 10440:1983			
20	CED 13 (26767) Revision	Laying and Fixing of Sloped Roof Coverings Using Plain and Corrugated Galvanized Steel Sheets		
	of: IS 12093:1987	- Code of Practice First Revision		
21	CED 13 (26768) Revision	No-Fines cast in situ cement concrete - Code of practice First Revision		
	of: IS 12727:1989			
22	CED 13 (26769) Revision	Use of fixing devices in Walls Ceilings and Floors of solid construction - Code of practice First		

	of: IS 1946:1961	Revision
23	CED 13 (26770)	Metal Framing Components for Drywall systems for Interiors application - Specification
24	CED 13 (26771)	Row Lock Bond Walling Technology - Code of Practice
25	CED 13 (26772)	Glazing Systems in Buildings Code of Practice

Drafts Standards in WC Stage			
SI. No.	SI. No. Doc No. Title		
	No Records Found		

	Draft Standards Completed WC Stage			
SI. No.	Doc No.	Title		
1	CED 13 (25733)	Design of Post - Installed Anchorage to Concrete - Code of Practice		
2	CED 13 (25734)	Testing and Assessment of Post-Installed Adhesive Anchoring Systems		
3	CED 13 (25735)	Testing and Assessment of Post-Installed Mechanical Anchoring Systems		

Finalized Draft Indian Standard			
SI. No.	Doc No.	Title	
No Records Found			

Finalized Draft Indian Standards under Print		
SI. No.	Doc No.	Title
1	CED 13 (23694)	STRUCTURAL GLAZING SEALANT SPECIFICATION

Total Published Standards:101 Total Standards Under development:29

## **Aspect Wise Report**

Product: 9
Code of Practices: 73
Methods of Test: 6
Terminology: 3
Dimensions: 1
System Standard: 0
Safety Standard: 0

Others: 9

Service Specification: 0 Process Specification: 0 Unclassified: 0

## Annexure-I :List of Indian Standards Withdrawn/Superseded

SI. No.	IS No. & Year	Title
1	SP 10 : 1975	Nomograms for Thickness of Masonry Walls
2	IS 1631 : 1960	Methods of test physical for industrial water
3	IS 1915 : 1961	Code of practice for steel bridges
4	IS 8358 : 1977	Performance test for wooden packing cases

Annexure-II: List of Indian Product Standards
---

SI. No.	IS No. & Year	Title

1	IS 10388 : 1982	Corrugated coir wood wool cement roofing sheets-Specification
	Reviewed In: 2020	
	Reaffirmed but not taken up	
	for revision	
2	IS 11433 (Part 1): 1985	Specification for one part gun-grade polysulphide- based joints sealants Part 1 General
	Reviewed In: 2020	requirements
3	IS 12118 (Part 1): 1987	Specification for two - Part polysulphide - Based sealants Part 1 general requirements
	Reviewed In: 2023	
4	IS 1834 : 1984	Hot Applied Sealing Compounds for Joints in Concrete- Specification First Revision
	Reviewed In: 2020	
5	IS 1838 (Part 1): 1983	preformed fillers for expansion joint in concrete pavement and structures non extruding and
	Reviewed In: 2020	resilient type Part 1 Bitumen impregnated fibre - Specification
6	IS 1838 (Part 2): 1984	preformed fillers for expansion joint in concrete pavement and structure non extruding and
	Reviewed In: 2020	resilient type Part 2 CNSL Aldehyde resin and coconut pith - Specification
7	IS 1838 (Part 3): 2011	Preformed Fillers for Expansion Joints in Concrete Pavements and Structures non-extruding and
	Reviewed In: 2021	resilient type Part 3 Polymer Based
8	IS 3629 : 1986	Structural Timber In Building - Specification
	Reviewed In: 2020	
9	IS 4891 : 1988	Specification for preferred cut sizes of structural timber First Revision
	Reviewed In: 2024	