

मानक भवन,9 बहादुरशाह जफर मार्ग नई, दिल्ली-110002 Manak Bhavan ,9 Bahadur Shah Zafar Marg, New Delhi-110002 Phones: 23230131 / 23233375 / 23239402 Website: www.bis.org.in , www.bis.gov.in

levie	ew Documer	nt					
asic D	<b>Details</b>						
	Sectional Committee No. & Title:			TED 2 - Automotive Primemovers, Transmission Systems and Internal Combustion Engine			
	IS No:			IS 3171 : Part 2 : 2006			
. Title :				Internal Combustion Engines - Fuel Injection Nozzle Holders - Part 2 : Screwin Injection Nozzle Holders, Types 20, 21, 21.1 and 27 for Pintle Nozzle Size 'S', Type B			
. Date of Previous Review:				February, 2021			
	Analysis	l(s). if any from which ass	istance had been drawn in the	formulation of this IS.			
S.No.			Whether the standard has				Action proposed
		l	No entry made i	n this table			
5.2 S	Referred	Referred standards (Title)	Since revised IS no. of the corresponding IS	Changes in the referred Standards since last review of IS	Changes in the referred stands which are affec standard under	ard cting the	Action proposed
No entry made in this table							
5.3 Any other standards available related to the subject & scope of the standard being reviewed (International/regional/other national/association/consortia, etc or of new or revision of existing Indian Standard).  S.No. Standard (No.) Standard (Title) Provisions that could be relevant while reviewing the IS Action proposed							
No entry made in this table							
5.4 T	Fechnical commen	nts on the standard receive	ed, if any.				
		Source	Clause of IS	Comment	Action	proposed	
S.No.	·•	Source	Charles of 15		'	• •	

5.5 Information available on relevant technical developments					
S.No.	Source	Development	Relevant clause of the IS under review that is likely to be impacted (Clause & IS No.)	Action proposed	
	No entry made in this table				

5.6 Issues arising out of changes in any related IS or due to formulation of new Indian Standard.						
S.No.	Related IS (revised or new)	Related IS Title	Provision in the IS under review that would be impacted & the clause no. or addition of new clause/provision	Changes that may be necessary in the Standards under review	Action proposed	
	No entry made in this table					

5.7 Any consequential changes to be considered in other IS.				
S.No.	Related IS to get impacted	Related IS Title	Requirements to be impacted	
No entry made in this table				

Othe	Other Details					
6.	Any other observation:					
7.	Upload Supporting Document(s)					
7.	1 ARP Report	67_9733_230914050339_ARP_Report.docx				
7.2 Draft Document		No Document Uploaded				
Recommendations - On the basis of the analysis of the mentioned above consideration of sectional committee the following aspects of the IS under review:			This standard is identical adoption of ISO 7026: 1997 which has not been revised ever since its publication by ISO/TC 22/SC 34. ISO 7026: 1997 was last reviewed and confirmed in 2019 by ISO Secretariat. In view of above, the committee may consider reaffirming IS 3171 (Part 2): 2006/ ISO 7026: 1997. The committee may also consider archiving the standard.			