

मानक भवन, 9 बहादुरशाह जफर मार्ग नई, दिल्ली-110002 Manak Bhavan ,9 Bahadur Shah Zafar Marg, New Delhi-110002 Phones: 23230131 / 23233375 / 23239402 Website: www.bis.org.in , www.bis.gov.in

Rev	Review Document					
Basic	Basic Details					
1.	Sectional Committee No. & Title:	TED 11 - Automotive Electrical Equipment and Instruments				
2.	IS No:	IS 1063: 1997				
3.	Title:	Automotive vehicles - Ml4 x 1.25 spark plugs with flat seating and their cylinder head housing - Specification (Second Revision)				
4.	Date of Previous Review:	March, 2017				

Review Analysis

5.1 Status of standard(s), if any from which assistance had been drawn in the formulation of this IS.						
S.No.	Standard (No.)	Standard (Title)	Whether the standard has since been revised	Major changes	Action proposed	
1	1919-1988	Road vehicles - Ml4 x 1.25 spark plugs with flat seating and their cylinder head housing'			ISO Standard withdrawn	

S.No.	Referred standards (No.)	Referred standards (Title)	Since revised IS no. of the corresponding IS	Changes in the referred Standards since last review of IS	Changes in the referred standard which are affecting the standard under review	Action proposed
1	IS IS 1062:1963	Method of test for spark plugs (revised)	IS 1062:2014			Information to be updated at Cl 2 and Cl 4.1, Table 3
2	IS 4218 (Part 1):1976	ISO Metric screw threads: Part 1 Basic and design profile (First Revision)	IS 4218 (Part 1): 2001			Information to be updated at Cl 2 and Cl 3.2.3
3	IS 4218 (Part 2):1976	Diameter pitch combinations (First Revision)	IS 4218 (Part 2) : 2001			Information to be updated at Cl 2 and C 3.2.3
1	IS 4218 (Part 3):1976	Basic dimensions for design profiles (First Revision)	IS 4218 (Part 3):1999			Information to be updated at Cl 2 and C 3.2.3
i	IS 4218 (Part 4):1976	Tolerancing system (First Revision)	IS 4218 (Part 4):2001			Information to be updated at Cl 2 and C 3.2.3
5	IS 4218 (Part 5):1979	Tolerances (First Revision)				No Change

5.3 Any other standards available related to the subject & scope of the standard being reviewed (International/regional/other national/association/consortia, etc or of new or revision of existing Indian Standard).					
S.No. Standard (No.) Standard (Title) Provisions that could be relevant while reviewing the IS Action proposed					
No entry made in this table					

5.4 Technical comments on the standard received, if any.						
S.No. Source Clause of IS Comment Action proposed						
No entry made in this table						

5.5 Information available on relevant technical developments					
S.No.	S.No. Source Development Relevant clause of the IS under review that is likely to be impacted (Clause & IS No.) Action proposed				
No entry made in this table					

S.No. Related IS (revised or new) Related IS Title Provision in the IS under review that would be impacted & the clause no. or addition of new clause/provision Changes that may be necessary in the Standards under review				Action proposed			
No entry made in this table							
5.7 Any	5.7 Any consequential changes to be considered in other IS.						
S.No. Related IS to get impacted Related IS Title Requirements to be impacted							

Othe	Other Details					
6.	Any other observation:	The Indian Standard has already assigned to M/s ACMA for review.				
7.	Upload Supporting Document(s)					
7.1	ARP Report	No Document Uploaded				
7.2	Draft Document	No Document Uploaded				
8.	Recommendations - On the basis of the analysis of the info availabl mentioned above consideration of sectional committee is solicited of the following aspects of the IS under review:					