

मानक भवन, 9 बहादुरशाह जफर मार्ग नई, दिल्ली-110002 Manak Bhavan ,9 Bahadur Shah Zafar Marg, New Delhi-110002 Phones: 23230131 / 23233375 / 23239402 Website: www.bis.org.in , www.bis.gov.in

Review Document					
Basic	Basic Details				
1.	Sectional Committee No. & Title:	TED 2 - Automotive Primemovers, Transmission Systems and Internal Combustion Engine			
2.	IS No:	IS 9262 : 1979			
3.	Title:	Recommendations for gear positions for road vehicles			
4.	Date of Previous Review:	November, 2020			
2.	IS No : Title :	Combustion Engine IS 9262: 1979 Recommendations for gear positions for road vehicles			

Review Analysis

5.1 Status of standard(s), if any from which assistance had been drawn in the formulation of this IS.					
S.No.	Standard (No.)	Standard (Title)	Whether the standard has since been revised	Major changes	Action proposed
1	DIN 73011:1983	Motor vehicles; gear lay-outs for manual transmissions in passenger cars	This standard has been withdrawn.		As this standard has been withdrawn, so assistance reference can be removed from the standard.

5.2 Stat	5.2 Status of standard referred in the IS.					
S.No.	Referred standards (No.)	Referred standards (Title)	Since revised IS no. of the corresponding IS	Changes in the referred Standards since last review of IS	Changes in the referred standard which are affecting the standard under review	Action proposed
1	Standard contains no Cross Referenced Standard.	n/a	n/a			

5.3 Any other standards available related to the subject & scope of the standard being reviewed (International/regional/other national/association/consortia, etc or of new or revision of existing Indian Standard).					
S.No.	Standard (No.)	Standard (Title)	Provisions that could be relevant while reviewing the IS	Action proposed	
No entry made in this table					

5.4 Technical comments on the standard received, if any.					
S.No.	Source	Clause of IS	Comment	Action proposed	
No entry made in this table					

5.5 Info	5.5 Information available on relevant technical developments					
S.No.	Source	Development	Relevant clause of the IS under review that is likely to be impacted (Clause & IS No.)	Action proposed		
	No entry made in this table					

5.6 Issu	5.6 Issues arising out of changes in any related IS or due to formulation of new Indian Standard.					
S.No.	Related IS (revised or new)	Related IS Title	Provision in the IS under review that would be impacted & the clause no. or addition of new clause/provision	Changes that may be necessary in the Standards under review	Action proposed	
	No entry made in this table					

5.7 Any consequential changes to be considered in other IS.					
S.No.	Related IS to get impacted	Related IS Title	Requirements to be impacted		
No entry made in this table					

Othe	Other Details					
6.	Any other observation:					
7.	Upload Supporting Document(s)					
7.1	7.1 ARP Report 67 16581 22102102014		13 ARP_Report.docx			
7.2	7.2 Draft Document 67_16581_221021020143		_Draft_Document.docx			
Recommendations - On the basis of the analysis of the info available as mentioned above consideration of sectional committee is solicited on the following aspects of the IS under review:		committee is solicited on	The standard may be revised taking into consideration the above recommendations.			