

मानक भवन,9 बहादुरशाह जफर मार्ग नई, दिल्ली-110002 Manak Bhavan ,9 Bahadur Shah Zafar Marg, New Delhi-110002 Phones: 23230131 / 23233375 / 23239402 Website: www.bis.org.in , www.bis.gov.in

Rev	Review Document										
Basic	Basic Details										
1.	Sec	Sectional Committee No. & Title:					TED 2 - Automotive Primemovers, Transmission Systems and Internal Combustion Engine				
2.	IS No:					IS/ISO 8178 : Part 9 : 2019					
3.	Tit	le :			Reciprocating internal combustion engines - Exhaust emission measurement - Part 9: Test cycles and test procedures for measurement of exhaust gas smoke emissions from compression ignition engines using an opacimeter						
4.	4. Date of Previous Review:						Not Review				
Revie	Review Analysis										
5.1	l Statı	us of standard(s), if an	y from which assi	stance had been drawn in	the fo	ormulation of this IS.				
S.I	No.	o. Standard (No.) Standard (Title) Whether the standard		Whether the standard l	has since been revised Majo			Major ch	Major changes Action prop		
1		N/A		NA							NA
5.2	5.2 Status of standard referred in the IS.										
S.I	No.	Referred standards (No.)		Referred standards (Title)	Since revised IS no. o the corresponding IS			ard ting the	Action proposed		
1		NA		NA							NA
	5.3 Any other standards available related to the subject & scope of the standard being reviewed (International/regional/other national/association/consortia, etc or of new or revision of existing Indian Standard).										
S.I	S.No. Standard (No.)		Standard (Title)		Provisions that could be relevant while reviewing the IS		Action proposed				
	No entry made in this table										
5.4	5.4 Technical comments on the standard received, if any.										
S.I	S.No. Source		Clause of IS		Comment Action p		proposed				
	No entry made in this table										

5.5 Info	5.5 Information available on relevant technical developments					
S.No.	Source	Development	Relevant clause of the IS under review that is likely to be impacted (Clause & IS No.)	Action proposed		
	No entry made in this table					

5.6 Issues arising out of changes in any related IS or due to formulation of new Indian Standard.						
S.No.	Related IS (revised or new)	Related IS Title	Provision in the IS under review that would be impacted & the clause no. or addition of new clause/provision	Changes that may be necessary in the Standards under review	Action proposed	
No entry made in this table						

5.7 Any consequential changes to be considered in other IS.

S.No. Related IS to get impacted Requirements to be impacted

No entry made in this table

Other	Other Details						
6.	Any other observation:						
7. Upload Supporting Document(s)							
7.1 ARP Report		67_26559_230811104406_ARP_Report.docx					
7.2	Draft Document	No Document Uploaded					
Recommendations - On the basis of the analysis of mentioned above consideration of sectional commit the following aspects of the IS under review:			As ISO 8178-9: 2019 has not been revised, the committee may decided to reaffirm standard.				