

मानक भवन, 9 बहादुरशाह जफर मार्ग नई, दिल्ली-110002 Manak Bhavan ,9 Bahadur Shah Zafar Marg, New Delhi-110002 Phones: 23230131 / 23233375 / 23239402 Website: www.bis.org.in , www.bis.gov.in

	Review Document							
asic De	etails							
S	Sectional Committee No. & Title:			Т	ΓED 14 - Air and Space V	ehicles Sectional Con	nmittee	
I	IS No:			I	S 13932 : 1994			
7	Title:				Aircraft - Electrical cables - Identification marking			
I	Date of Previous R	eview:		N	March, 2021			
	Analysis atus of standard(s), if any from which ass	istance had bee	n drawn in the	formulation of this IS.			
S.No.	Standard (No.) Standard (Title)			Whether the standard has since been revised		Major changes	anges Action proposed	
			Aircraft electric cables â 🕮 Identification Marking		ISO 2574:1974 has been revised as ISO 2574:1994		Revised ISO standard ma be adopted.	
5.2 Sta S.No.	Referred standards (N	Referred	Since revision the corresponding to the correspondi	sed IS no. of ponding IS	Changes in the referred Standards since last review of IS	Changes in the referred stands which are affect standard under	ard cting the	Action proposed
			N	No entry made in	n this table			
			subject & seen	e of the standa	rd being reviewed (Inter	national/regional/ot	her	
		s available related to the asortia, etc or of new or a Standard (No.)		ting Indian Star			Action p	proposed
nation		nsortia, etc or of new or	Standard	ting Indian Star	Provisions that co while reviewing th		Action p	oroposed
S.No.	nal/association/con	nsortia, etc or of new or	Standard	ting Indian Star	Provisions that co while reviewing th		Action p	oroposed
S.No.	nal/association/con	Standard (No.)	Standard	ting Indian Star	Provisions that co while reviewing th	e IS	Action p	proposed

5.5 Info	5.5 Information available on relevant technical developments				
S.No.	Source	Development	Relevant clause of the IS under review that is likely to be impacted (Clause & IS No.)	Action proposed	
	No entry made in this table				

5.6 Issues arising out of changes in any related IS or due to formulation of new Indian Standard.					
S.No.	Related IS (revised or new)	Related IS Title	Provision in the IS under review that would be impacted & the clause no. or addition of new clause/provision	Changes that may be necessary in the Standards under review	Action proposed
No entry made in this table					

5.7 Any consequential changes to be considered in other IS.

Requirements to be impacted

No entry made in this table

Related IS Title

S.No.

Related IS to get impacted

Other	Other Details						
6.	6. Any other observation:						
7.	7. Upload Supporting Document(s)						
7.1 ARP Report		67_5740_221213101622_ARP_Report.docx					
7.2	Draft Document	No Document Uploaded					
Recommendations - On the basis of the analysis of the mentioned above consideration of sectional committee the following aspects of the IS under review:			It is proposed that IS 13932 may be revised and ISO 2574:1994 may be adopted.				