## BUREAU OF INDIAN STANDARDS (ERL, KOLKATA)

Our Ref: EROL/SC/50 09.03.2023

Subject: Acute shortage of PDW/PNMW and Electrical samples at ERL

The following samples may be rushed to ERL as the testing facility remains under-utilized due to acute shortage of sample:

Sl.	ISs Nos.	Testing Field	Remarks
No.			
01.	IS 398(P-1), IS 398 (P-4), IS 3975, IS 5950, IS 5484, IS 191	Elec	Limitations in testing facilities are given on BIS website / Intranet
02.	IS 398(P-2), IS 398(P-5), IS 694, IS 1554(P-1), IS 1554 (P-2), IS 2465, IS 2593, IS 7098 (P-1), IS 7098 (P-2), IS 9857, IS 9968( P-1), IS 9968 (P-2), IS 12776, IS 14255, IS 14494	Elec	
03.	IS14543 ,IS 13428	Chem	
04.	IS14543 ,IS 13428	Microbiology	

This issues with the approval of Competent authority

OIC (Sample cell)

To all ROs/BOs/BIS Labs/CMD-I/CSMD

Copy to: Head(LPPD)/Head (LRMD)