## केन्द्रीय मुहर विभाग - ॥

हमारा संदर्भ- केन्द्रीय मुहर विभाग-3/16: IS 1363 (Part 3) दिनांक :09 10 2018

विषय: अनुपालन हेतु एस आई टी

सभी शाखा कार्यालय से आग्रह है कि एस आई टी का अनुपालन तत्काल प्रभाव से सुनिश्चित करें।

> (अमित कुमार) वैज्ञानिक 'सी' (सी एम डी-III)

### प्रमुख (सी एम डी-॥।)

सभी क्षेत्रीय/शाखा कार्यालय आई टी एस विभाग – बीआईएस इंट्रानेट पर अपलोड करने हेत्

#### **CENTRAL MARKS DEPARTMENT-III**

Our Ref: CMD-3/16: IS 1363 (Part 3) Date: 09 10 2018

Subject: SIT for IS 1363(Part 3):2018 – Hexagon Head Bolts, Screws and Nuts of Product Grade 'C' – Part 3 (Style1) Hexagon Nuts (Size Range M 5 to M 64).

This has reference to the subject mentioned above.

BOs may kindly ensure implementation of the SIT with immediate effect.

Amit Kumar Sc. C (CMD III)

#### Head (CMD - III)

Circulated to: All ROs/BOs

Copy to: ITS for hosting on Intranet

# SCHEME OF INSPECTION AND TESTING FOR CERTIFICATION OF HEXAGONAL NUTS (STYLE 1) (SIZE RANGE M5 to M 64) ACCORDING to IS 1363 (Part 3):2018

- **1. LABORATORY** A laboratory shall be maintained which shall be suitably equipped (as per the requirement given in column 2 of Table 1) and staffed, where different tests given in the specification shall be carried out in accordance with the methods given in the specification.
- **1.1** The manufacturer shall prepare a calibration plan for the test equipment.
- **2. TEST RECORDS** The manufacturer shall maintain test records for the tests carried out to establish conformity.
- **3. LABELLING AND MARKING** As per the requirements of IS 1363 (Part 3).
- **4. CONTROL UNIT** All nuts of same property class and designation manufactured in a day shall constitute a control unit.
- **HEAT TREATMENT BATCH:** All the nuts of same property class and designation heat treated together at the same time shall constitute a heat treatment batch
- **5. LEVELS OF CONTROL** The tests as indicated in column 1 of <u>Table 1</u> and the levels of control in column 3 of <u>Table 1</u>, shall be carried out on the whole production of the factory which is covered by this plan and appropriate records maintained in accordance with paragraph 2 above.
- 5.1 All the production which conforms to the Indian Standard and covered by the licence should be marked with Standard Mark.
- **6. REJECTIONS** Disposal of non-conforming product shall be done in such a way so as to ensure that there is no violation of provisions of BIS Act, 2016.

TABLE 1

(1) Test Details				(2) Test equipment requirement	(3)		
					Levels of Control		
Cl.	Requirement	Test Methods		R: required (or)	No. of Sample	Frequency	Remarks
		Clause	Reference	S: Sub- contracting permitted			
3.	Dimensions	3	IS 1363 (Part 3)	R	As per sampling plan given in IS 1367 (Part 17)		
4	Material	4 Table 3	IS 1363 (Part 3) IS 1367 (Part 6) / ISO 898 (Part 2)	S	One	Each consignment	No further testing is required, if accompanied with test certificate or ISI marked
	Threads requirement		IS 4218 (Part 3) IS 14962 (Part 1)	R	As per sampling plan given in IS 1367 (Part 17)		

TESTS							
Stress under proof load	9.1	IS 1367 (Part 6) / ISO 898 (Part 2)	R	Two	Every 7 <sup>th</sup> control unit	In case of any failure, twice the number of sample shall be tested from the same control unit/heat treatment batch for those	
Hardness	9.2	IS 1367 (Part 6) / ISO 898 (Part 2)	R	Three	Every Heat treatment batch	characteristics in which failure has occurred. In case of any further failure the control unit/heat treatment batch shall be	
Surface Integrity inspection	9.3	IS 1367 (Part 6) / ISO 898 (Part 2)	R	Every half be checked	f hour samples to	rejected and shall not be marked with BIS standard mark .Further each control unit corresponding to the property class in which the failure had occurred shall be tested till sample for three consecutive control units pass after which the earlier frequency can be restored.	
Finish/ Coating							
Electroplating		IS 1367(Part 11)	R	As per Sar given in 1	mpling plan Note 1	Different electroplating or other finish may be given as agreed	
Non - Electrolytically applied zinc flake coating		ISO 10683	R			between customer and supplier	

**NOTE 1:** Sampling plan for Finish/coating test:

Total number of nuts	Number of test samples			
in batch				
Upto and including 500	3			
501 upto and including 35,000	5			
Over 35,000	8			

NOTE-2: Sub-contracting is permitted to a laboratory recognized by the Bureau or Government laboratories empanelled by the Bureau.

**NOTE-3:** Levels of control given in column 3 are only recommendatory in nature. The manufacturer may define the control unit/batch/lot and submit his own levels of control in column 3 with proper justification for approval by BO Head.