Annes - L

BUREAU OF INDIAN STANDARDS (Harvana Branch Office)

Date: 07.10.2024

Our Ref : HRBO/Discrete Visit/CML-9100106398

Subject : Discreet Visit for misuse of CML-9100106398

Date of Visit: 03.10.2024

Place of Visit : Near Chaupal Restaurant, Ladwa, Kurukshetra.

Purpose of Visit: Complaint is regarding Misuse of ISI mark on Paver Block on expired CML-9100106398

لمبي) Details of Investigation on 03، 10.2024:

A discrete Visit was carried out on 03.10.2024 to check misuse of ISI mark with CML-9100106398. Undersigned visited the location where misuse was reported earlier from other means. Undersigned found huge stock piled up outside the factory premise. Some Manufacturing machineries were also visible from outside which might have been used to manufacture Concrete paver blocks. On examining the paver blocks closely, paver block was found to be marked as ISI mark CML-9100106398 with Brand Name as "SSI" as Grade- M40. CML was found to be expired when checked on the BIS care app, Screenshot is attached as Annex-A. CML on paver can be seen on paver block as attached in Annex-B. Some photos of the stock were also taken as a proof which has been attached as Annex-C. Name of the firm was written as "Divine Tile Factory" outside the wall of the factory.

Conclusion: Factory was found to be applying and using an expired license and does not have a valid license for the cause.

Recommendations: In view of above, Search and Seizure may be planned at the identified location.

Regards,

Niraj Kumar Mahato Scientist 'C'

HRBO X Ju 15/110/24

Annex-A



Licence Details

Name of Manufacturer	DIVINE J.C.B & BULDING MATERIAL
Address of Manufacturer(If mentioned on Product or Packing)	NEAR BAN WALA PEER,RADAUR ROAD,LADWA
District:	KURUKSHETRA
State:	HARYANA
Name of Product :	Concrete Paving Blocks - Specification (First Revision)
IS No.:	IS 15658 : 2006
valid till :	28-Apr-2022
Varieties Covered :	SINGLE LAYER, UN-PIGMENTED & WITHOUT OPTIONAL REQUIREMENTS FOR GRADE: M-40 & THICKNESS: 80 mm(Variety)SINGLE LAYER, UN-PIGMENTED & WITHOUT OPTIONAL REQUIREMENTS FOR GRADE: M-35 & THICKNESS: 60 mm & 80 mm
Current status :	EXPIRED
Register Complaint	Reset



