

**Bureau of Indian Standards**  
(Bangalore Branch Office Laboratory)

Ref:BNBOL/Mech/Sample


27 Jan 2021


**Subject: Shortage of Samples in Mechanical Laboratory**

Mechanical laboratory of BNBOL is having acute shortage of samples for testing. All RO/BOs are requested to send the samples for Mechanical testing as per the test facility available on BIS website.

However, as the equipment is out of order, hydraulic characteristics test as per IS 12786, is not carried out and samples may be sent accordingly.

Head(BNBOL)

  
27/01/2021

  
OIC(Mechanical)

All RO/BOs

ITSD: with a request to upload this circular on BIS Intranet

**भारतीय मानक ब्यूरो**

(बैंगलोर शाखा कार्यालय प्रयोगशाला)

संदर्भ: बीएनबीओ/यांत्रिक/नमूना


27 Jan 2021


**विषय : यांत्रिक प्रयोगशाला में नमूनों की कमी**

परीक्षण के लिए यांत्रिक प्रयोगशाला बीएनबीओएल में नमूनों की भारी कमी है. सभी आरहे/बीओ से अनुरोध है कि परीक्षण के लिए नमूने बीआईएस वेबसाइट पर उपलब्ध परीक्षण सुविधा के अनुसार भेजे ।

हालाँकि, उपकरण खराब होने के कारण, IS 12786 के अनुसार हाइड्रोलिक विशेषताओं का परीक्षण नहीं किया जाता है, और नमूने उसी के अनुसार भेजे जा सकते हैं ।

प्रमुख(बीएनबीओएल)

  
27/01/2021

  
ओआईसी (यांत्रिक)

सभी आर ओ/बी ओ

आईटीइसडी: इस परिपत्र को BIS इंटरनेट पर अपलोड करने के अनुरोध के साथ