



F_M = MAXIMUM FORCE
 X_M = DISPLACEMENT FOR MAXIMUM FORCE
 F_{10} = FORCE AT 10 PERCENT DEFORMATION
 X_{10} = DISPLACEMENT FOR 10 PERCENT DEFORMATION

FIG. 1 ZERO POINT DETERMINATION