IS: 10810 (Part 42) – 1984 (Reaffirmed 2001)

Indian Standard

METHODS OF TEST FOR CABLES

PART 42 RESISTIVITY TEST OF ARMOUR WIRES AND STRIPS AND CONDUCTANCE TEST OF ARMOUR (WIRES/STRIPS)

1. SCOPE - Covers method for determination of the resistivity of the armour wires and strips used in electric cables and the conductance of the armour of electric cables.