IS 13416 (Part 3): 1994

(PREVIEW)

Indian Standard

PREVENTIVE MEASURES AGAINST HAZARDS AT WORKPLACES -RECOMMENDATIONS

PART 3 DISPOSAL OF DEBRIS

1 SCOPE

This standard (Part 3) lays down the classification, and methods of collection and removal of debris (MULBA) and preventive measures to be taken during various operations so as to avoid accidents and injuries.

2 REFERENCES

The Indian Standard IS 2925:1984 'Specification for industrial safety helmets (*second revision*)' is a necessary adjunct to this standard.