Indian Standard METHOD OF MEASUREMENT OF LAMP CAP TEMPERATURE RISE

1. SCOPE

1.1 This standard specifies the standard method of measurement of lamp cap temperature rise which is to be used when testing lamps for general lighting services for compliance with IS: 418-1978*.

It also describes the test lampholders to be used for lamps fitted with E27, E40 and B22/25 x 26 caps.

^{*}Specification for tungsten filament general service electric lamps (third revision).