
Fwd: NON BIS COMPLIANT MATERIAL SOLD BY THIS DEALER

From : CMED BIS <complaints@bis.gov.in>

Mon, Jun 24, 2024 12:12 PM

Subject : Fwd: NON BIS COMPLIANT MATERIAL SOLD BY THIS DEALER

📎 1 attachment

To : CSMD Department <csmddept@bis.gov.in>**Cc :** Head CSMD <headcsmd@bis.gov.in>, HeadCMED <headcmed@bis.gov.in>**Reply To :** CMED BIS <complaints@bis.gov.in>

Sir/Madam,

Trailing mail may please be examined for necessary action.

Regards,
Deepak Lodhwal
DD/Sc-C, CMED

From: jaipatelbharat@gmail.com**To:** "CMED BIS" <complaints@bis.gov.in>, "CMD I" <cmd1@bis.gov.in>, bis@bis.gov.in, "BIS DG Secretariat" <dg@bis.gov.in>, "BIS Raipur Branch Office" <rpbo@bis.gov.in>, "BIS I Bangalore Branch Office" <bnbo@bis.gov.in>, "Mr Darpan Jain" <js1tpd-doc@nic.in>, "Ghaziabad Branch Office GZBO Uttar Pradesh" <gzbo@bis.gov.in>, "SUBOBIS" <subobis@bis.gov.in>, "RAKESH BIHARI" <rakesh.bihari@gov.in>, "BNBOL BNBOL" <bnbol@bis.gov.in>, "CC, Chennai Customs" <ccchennaizone.tn@nic.in>, "CCU Customs Bengaluru Zone" <ccu-cusblr@nic.in>, "VINITH KUMAR G" <vinith.g@bis.gov.in>, "YOGESH CHITTE" <yogeshs.chitte@gov.in>**Sent:** Saturday, June 22, 2024 4:08:01 PM**Subject:** NON BIS COMPLIANT MATERIAL SOLD BY THIS DEALER

DEAR

I WOULD LIKE TO INFORM YOU THAT FLUX CORED WIRE (IS 15769 2008) WHICH IS COMPULSORY TO HAVE BIS MARK, THERE ARE DEALERS WHO ARE BUYING THIS MATERIAL WHICH IS ILLEGALLY IMPORTED FROM CHINA THROUGH MISDECLARATION IS BEING SOLD ILLEGALLY.

THE PLACE WHERE THIS MATERIAL IS STORED IS MENTIONED BELOW REQUESTING THE AUTHORITIES TO TAKE IMMEDIATE ACTION TO AVOID THIS INFERIOR MATERIAL TO ENTER INTO OUR CORE INFR SEGMENT AS THIS CAN BE DANGEROUS IF WELDING FAILS. I REQUEST TEAM BIS, EVEN CUSTOM AUTHORITIES TO KEEP CLOSE CHECK AS THIS CAN BE DANGEROUS FOR OUR INFRASTRUCTURE. THIS ALL MATERIAL COMES THROUGH CHINA AND AS A MISDECLARATION.

DETAILS OF THE DEALER SELLING:

MANGALAM ENTERPRISES

251, SHASTRI MARKET, SECOND FLOOR, INDORE, MADHYA PRADESH

WWW.MANGALAMGLOBAL.COM

THANKS AND REGARDS

JAI PATEL
RTI ACTIVIST

BHARAT (INDIA)



MANGALAM ENT FLUX CORED WIRE.jpg
264 KB